

Belzona 1111 & Belzona 4311 reconstructs and protects chemical pump


ID: 8140

Industry: Sugar
Application: CEP-Centrifugal Pumps
Substrate: Cast Iron
Products: * Belzona 1111 (Super-Metal) ,
* Belzona 9111 (Degreaser) ,
* Belzona 4311 (Magma CR1) ,
* Belzona Flange Face Forming Kit. ,

Customer Location: Switzerland
Application Date: 15.11.2019

Problem

The chemicals attacked or completely destroyed the flange surfaces and parts of the housing.



Photograph Descriptions

- * Image 1: Damaged Pump ,
- * Image 2: Flange Reform ,
- * Image 3: Internal Coating Complete ,
- * Image 4: Flange Reformed. ,

Application Situation

KSB centrifugal pump which is used for pumping chemicals, in a sugar factory.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Application Method

Re-built with Belzona 1111 with the use of the Flange Face forming kit and then protected with a Belzona 4311 in accordance with Belzona Know-How CEP-03.

Belzona Facts

The client trusted Belzona with the re-build of the flanges and coating of the internal lining due to the experience of the local distributor with repairing pumps in the local Swiss market.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

