

# Belzona renovate a process tank


ID: 8169

Industry: Food & Drink  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Steel  
Products: \* Belzona 5892 ,

Customer Location: France  
Application Date: January 2020

## Problem

The internal lining of the tank was corroded due to the products being acidic when they are at high temperatures.



## Photograph Descriptions

\* 1 - Tank after grit blasting 2 - During application of Belzona 5892 3 - Tank after complete coating ,

## Application Situation

Internal lining of a wheat starch milk tank in a factory

## Application Method

Application was carried out in accordance with Belzona System Leaflet TCC-5. The tank was previously grit blasted to remove the rust before applying 2 coats of Belzona 5892. Small retouches were made before the coating system was post-cured with steam.

## Belzona Facts

The replacement of the tank would have cost €1,000,000 whereas the Belzona repair was 10 times less (€100,000). The customer was quick to chose Belzona as the previous competitor coatings have failed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve