

# Protection of a brand new secondary containment area with Belzona

ID: 8170

Industry: Chemical & Petrochemical  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 4181 (AHR Magma Quartz) ,

Customer Location: Chemical Company - France  
Application Date: January 2020

## Problem

The customer wished for "heavy-duty" protection of this brand new containment area before installing the machines, in order to effectively protect this area.



## Photograph Descriptions

- \* 1 - Secondary containment area newly created ,
- \* 2 - Area after surface preparation ,
- \* 3 - During the application ,
- \* 4 - Area completely coated and protected with Belzona 4181 ,

## Application Situation

Brand new secondary containment area 216m2 where reactor pumps with hydrochloric acid at 80°C will be installed.

## Application Method

The area was cleaned and prepared before that the application of Belzona 4181 was completed in accordance with Belzona System Leaflet FPA-03.

## Belzona Facts

Belzona 4181 had successfully passed all the client tests (especially the high temperature) for this plant where they produce synthetic salt. Area of 216 m2, carried out in 5 days for a 4 men team. Overall cost 74,000€.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

*Copyright © Belzona International Limited 2025*

