

# Belzona Repair Strainers

ID: 8180

Industry: *Marine*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Namibia*  
Application Date: *14 October 2019*

Substrate: *Cast iron*  
Products: *\* Belzona 1111 (Super Metal) ,*  
*\* Belzona 1321 (Ceramic S-metal) ,*  
*\* Belzona 5811 (Immersion grade) ,*

## Problem

*Strainers badly eroded*



## Photograph Descriptions

- \* 1. Strainer badly corroded ,
- \* 2. Strainer Flange ,
- \* 3. After grid blast ,
- \* 4. Final product done with Belzona 1111 and Belzona 1321, with Belzona 5811 on the outside. ,

## Application Situation

Fishing vessel strainers

## Application Method

Application was carried out according to the system leaflet SOS-1 & SOS-2

## Belzona Facts

These strainers are very badly damaged and is very costly to repair or manufacture new ones. The only economical way to repair

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

then is with Belzona.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

