

# Belzona repair on a thruster body

ID: 8182

Industry: *Marine*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Namibia*  
Application Date: *2020-03-02.*

Substrate: *Steel*  
Products: *\* Belzona 1111 (Super Metal) ,*  
*\* Belzona 1321 (Ceramic S-Metal) ,*

## Problem

*Heavy wear on body of thruster due to sea water.*



## Photograph Descriptions

\* 1. Before 2. after repair with Belzona 1111 and Belzona 1321. ,

## Application Situation

Thruster body repair.

## Application Method

Application was carried out according to the Belzona Know-How system leaflet SOS-2

## Belzona Facts

Belzona offered a repair system that was economically competitive and could protect against future wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve