

Belzona repair on a thruster body

ID: 8182

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Namibia*
Application Date: *2020-03-02.*

Substrate: *Steel*
Products: ** Belzona 1111 (Super Metal) ,*
** Belzona 1321 (Ceramic S-Metal) ,*

Problem

Heavy wear on body of thruster due to sea water.



Photograph Descriptions

* 1. Before 2. after repair with Belzona 1111 and Belzona 1321. ,

Application Situation

Thruster body repair.

Application Method

Application was carried out according to the Belzona Know-How system leaflet SOS-2

Belzona Facts

Belzona offered a repair system that was economically competitive and could protect against future wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Copyright © Belzona International Limited 2025