

# Belzona 5892 Protects Cement Plant Walls

ID: 8198

Industry: Cement  
Application: WPA-Wall Problem Areas  
Substrate: Steel  
Products: \* Belzona 5892 ,

Customer Location: Poland  
Application Date: 2019

## Problem

*The temperature in the furnace bag filters has caused corrosion of the bag filter walls.*



## Photograph Descriptions

- \* Oven bag filter before protection ,
- \* Grit blasting filter surface ,
- \* First Layer of Belzona 5892 ,
- \* Oven bag filter after 2nd Layer of Belzona 5892 ,

## Application Situation

Damaged walls of the furnace bag filters on a Cement plant.

## Application Method

Abrasive grit blasting, dust removal of wall surfaces and bag filter sieves. Then a Belzona 5892 two coat system was applied.

## Belzona Facts

A cost effective solution for the customer using Belzona 5892 was a key driver however the back up service and support from the local distributor was key to the client making the decision to use Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025