

Belzona 4111 repairs a floor in a manufacturing facility.

ID: 8201

Industry:

Customer Location: Poland

Application:

Application Date: 2019

Substrate: Concrete

Products: * Belzona 4111(Magma-Quartz) ,
* Belzona 4151(Magma-Quartz resin) ,

Problem

Carts in a manufacturing facility were damaging the floor due to the heavy traffic, weight of the carts, and the steel wheels.



Photograph Descriptions

* 1: Ensure cavity's are clean and prepared. 2: Fill cracks and cavities with Belzona 4111 3: Belzona 4111 composite application in liquid form 4: Completed Application ,

Application Situation

Floor damage due to heavy traffic in a manufacturing facility.

Application Method

The surface was prepared by cutting out the floor cracks and vacuuming the surface. Belzona 4151 was used to impregnate the floor then Belzona 4111 was applied.

Belzona Facts

Little down time was crucial for the client in this manufacturing facility, which is why they opted for Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve