

Paper & Pulp Plant tank repaired with Belzona 5892

ID: 8203

Industry: *Pulp & Paper*

Customer Location: *Poland*

Application: *TCC-Tanks and Chemical Containment Areas*


Application Date: *2019*

Substrate: *Steel*

Products: ** Belzona 5892 Belzona 9121 (Thinners),*

Problem

Internal of the condensate tank at the paper & pulp plant was suffering from corrosion.



Photograph Descriptions

* Condensation Tank Application of Belzona 5892 Belzona 5892 2nd layer Application Complete ,

Application Situation

Condensate tank suffering from corrosion.

Application Method

Substrate grit blasted to surface cleanliness (Sa21/2). Followed a profile check for the min surface roughness of 75 microns. Degreasing surfaces with Belzona degreaser 9121 and applied Belzona 5892 in a two coat system. The application was completed in accordance with Belzona System Leaflet TCC-05.

Belzona Facts

Belzona have proven solutions for the paper & pulp industry and used the local distributor for back up service and support.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

