

# Paving slab walkway repair with Belzona

ID: 8305

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Stone Paving Slabs

Products: \* Belzona 4111 (Magma Quartz) ,



\* Belzona 4911 (TX Conditioner) ,

Customer Location: Scotland

Application Date: 2019 & 2020

## Problem

*Removing & replacing the paving slabs would have been a highly disruptive & costly undertaking. A durable & aesthetically pleasing repair solution was required that could be applied to the slabs whilst they remained in place.*



## Photograph Descriptions

- \* Paving slabs original ,
- \* Wear & weathering of the existing slabs ,
- \* Belzona 4111 colour matched & applied ,

## Application Situation

Marshall's paving slabs had been installed on a domestic walkway as step treads. These slabs had started to deteriorate through wear, age & weathering. The slabs had lost their original colour & now had a dull appearance. The slabs were then replaced at the expense of the installer but after a further six years the replacements had also deteriorated. A permanent solution was required.

## Application Method

The Belzona 4111 Base was colour matched to the original Marshall's paving slabs using the Grey/Sandstone shades & cement pigments. Belzona 4911 TX Conditioner was applied to the areas followed by the mixed Belzona 4111 Magma Quartz.

## Belzona Facts

By using the Belzona solution there was no need for the removal of the existing paving slabs. These slabs could remain in place whilst being protected by a hard wearing & aesthetically pleasing material.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve