

# Belzona Protects Pharmaceutical Plant Floor

ID: 8317

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 5231 (SG Laminate) ,

Customer Location: Italy  
Application Date: 2017

## Problem

*This plant floor and sump area were located outside and the outdoor roof didn't cover the full area, this was causing the concrete to degrade over time. Also, due to process there was occasional chemical spillages onto the concrete and therefore the client wanted the concrete sealing.*



## Photograph Descriptions

- \* Before application ,
- \* Before application ,
- \* Final application ,
- \* Final application ,

## Application Situation

Installation of a new positive grip flooring system on an outdoor concrete floor.

## Application Method

This application was carried out in accordance with system leaflet FPA-03. The concrete floor was prepared through grinding and cleaned before applying the Belzona 5231 with rollers.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

## Belzona Facts

The whole application was carried out within 2 days without having to disturb the process.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

