

Continuous Casting Ladle Turret Bearing Repair with Belzona

ID: 8386

Industry: Steel & Metal Processing
Application: MPT-Mechanical Power Transmission

Customer Location: Steel Plant South Wales
Application Date: October 2020

Substrate: High Carbon Steel
Products: * Belzona 1121 (XL metal) ,
* Belzona 9111 (Cleaner Degreaser) ,
* Belzona 9411 (Release Agent) ,

Problem

The collapse of one bearing had damaged the bearing seat area putting the machine out of use. The shaft diameter is 450mm and the width of the damage was 200mm with up to 6mm in depth. There were no spares available and due to difficulty in machining the shaft and the tight tolerances needed, Belzona were asked if we could help.



Photograph Descriptions

- * Top of the damaged area on the shaft and how access was difficult ,
- * Overview of the shaft and bearing housing area ,
- * Former manufactured for this repair ,
- * Finished repair after removal of the former ,

Application Situation

The client had a bearing failure on the Ladle turret, causing damage to the shaft seat. the turret carries two ladles which are full with molten steel, one is draining the steel into the Concast casting a steel slab, whilst the other is being recharged. the total weight of each ladle whilst full of metal is 500 tons. This Failure had brought steel production to a standstill on the production line.

Application Method

System Leaflet MPT-2, for rebuilding damaged shafts using forming techniques

Belzona Facts

The overall cost for the Belzona material were close to £800.00, the cost saving to the client were in the thousands of pounds in lost production and renewal of parts.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

