

Belzona Flexible Membrane Seals Leaking Concrete Garage roof

ID: 8394

Industry: Buildings & Structures

Customer Location: Malacky, Slovakia

Application: RPA-Roof Problem Areas

Application Date: 2015

Substrate: Concrete

Products: * Belzona 3111 (Flexible Membrane) ,

Problem

Water, leaking through the concrete roof, was falling on the warehous goods and damaging it.



Photograph Descriptions

- * 1. Leaking concrete garage roof ,
- * 2. Application of Belzona 3911 to concrete surfaces ,
- * 3. Application of Belzona 3111 ,
- * 4. Ready to use ,

Application Situation

Leaking concrete garage roof

Application Method

Application completed in accordance with a modified version of Belzona Know-How System Leaflet RPA-10

Belzona Facts

Sun and rain are able to destroy a lot of roof protection systems. Belzona 3111 system shows to be long lasting and perfect protected water proof system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

