

Pharmaceutical Plant uses Belzona Safety Grip System


ID: 8418

Industry: Food & Drink
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 5231 (SG Laminate) ,
* Belzona 1821 (Fluid Metal) ,
* Belzona 9211 (Supergrip Aggregate) ,
* Belzona 5233 ,

Customer Location: Switzerland
Application Date: May 2020

Problem

The exterior flooring was an issue when the Pharmaceutical Plant forklift trucks were operating outside, causing the forklifts to slip when loading and un-loading.



Photograph Descriptions

- * Image 1: Application of Belzona 5231 ,
- * Image 2: Strips of Belzona 5231 ,
- * Image 3: Close up ,
- * Image 4: Final Application Complete ,

Application Situation

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

The client required a form of grip system for exterior use to stop any potential accidents or problems.

Application Method

Areas of concrete were repaired with Belzona 4111. The Belzona 5231 was then applied in accordance with System leaflet FPA-8 to the concrete and then the Belzona 1821 and Belzona 9211 grip system was used to create a safety grip system then overcoated with Belzona 5233 for increased UV Stability.

Belzona Facts

Belzona was used due to already been applied in other areas of the plant and knowing that Belzona performs very well they opted for Belzona on this particular health and safety issue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

