

# Belzona Keeps Fishing for 20 years.

ID: 8427

Industry: Marine

Application: FPA-Floor Problem Areas

Substrate: Steel

Products: \* Belzona 4911 (Magma TX conditioner) ,  
\* Belzona 4111 (Magma Quartz) ,

Customer Location: Perth, Western Australia

Application Date: 2000 and 2020

## Problem

Now in 2020, some 20 years after the original application, some localized areas required attention and re-laying of Belzona 4111.



## Photograph Descriptions

- \* 1. Fishing Trawlers ,
- \* 2. Stern ramp deck prior to repair ,
- \* 3. Close up of original 20 year old Belzona 4000 product ,
- \* 4. New repairs complete. ,

## Application Situation

The area adjacent to the stern ramp of the trawling vessel is a constant trafficable area for the crew as well as weighted nets full of the catch of the day being dragged across the deck. Back In 2000 the engineer in charge applied one of the Belzona 4000 products to the deck area for non slip and durability.

## Application Method

The localized areas were mechanically abraded and the Belzona 4111 was troweled into the areas to be patched.

## Belzona Facts

The same engineer applied both Belzona products some 20 years apart - it was very evident that the original Belzona was extremely durable and robust making the decision to carry out the patch repairs with Belzona a very easy one.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve