

# BELZONA REPAIRS TO ROOFTOP EXHAUST DUCTING

ID: 843

Industry: *General Industry*  
Application: *VPF-Valves, Pipes and Fittings*  
Substrate: *Galvanized metal*  
Products: *Belzona® 2211 (MP Hi-Build Elastomer)*

Customer Location: *Pet food manufacturer, MO*  
Application Date: *April 2007*

## Problem

*Joints were leaking allowing escape of unpleasant gases into the neighbourhood leading to many complaints.*



## Photograph Descriptions

\* First duct joint , \* Close up of first joint repair , \* Second joint repair ,

## Application Situation

Rooftop exhaust ductwork

## Application Method

Application carried out using a modified Belzona System VPF-11a

## Belzona Facts

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve