

# BELZONA REPAIRS TO ROOFTOP EXHAUST DUCTING

ID: 843

Industry: General Industry  
Application: VPF-Valves, Pipes and Fittings  
Substrate: Galvanized metal  
Products: Belzona® 2211 (MP Hi-Build Elastomer)

Customer Location: Pet food manufacturer, MO  
Application Date: April 2007

## Problem

Joints were leaking allowing escape of unpleasant gases into the neighbourhood leading to many complaints.



## Photograph Descriptions

\* First duct joint , \* Close up of first joint repair , \* Second joint repair ,

## Application Situation

Rooftop exhaust ductwork

## Application Method

Application carried out using a modified Belzona System VPF-11a

## Belzona Facts

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2025

  
**BELZONA®**  
Repair • Protect • Improve