

Belzona Protects New Butyl Glycol Esters Tanks

ID: 8446

Industry: *Chemical & Petrochemical*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: ** Belzona 4311 (Magma CR1),*

Customer Location: *Lubin, Poland*
Application Date: *June 2020*

Problem

Internal corrosion of tanks damaged due to corrosion and failure of previous coating.



Photograph Descriptions

- * 1. Asset Location ,
- * 2. Butyl glycol esters tanks ,
- * 3. Previous coating corrosion protection damage. ,
- * 4. Inspection after one year ,

Application Situation

Butyl glycol esters tanks needed a protective coating.

Application Method

Application was carried out in accordance with Belzona system Leaflet TCC-5.

Belzona Facts

The client had used a cheap coating in containment area first and after it failed decided to spend a little more money to make it last a long time. Belzona 4311 was applied into the internal lining of the tank and is still in good condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve