

Belzona Helps Protect Offshore Platform Legs At A Waterline

ID: 8447


Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Baltic Sea
Application Date: September 2020

Substrate: Steel
Products: * Belzona 5831 (ST Barrier),

Problem

Corrosion of platform legs in the splash zones.



Photograph Descriptions

- * 1. Corroded platform legs ,
- * 2. Surface preparation ,
- * 3. Belzona 5831 in use. ,
- * 4. Platform ,

Application Situation

Original corrosion protection damaged on platform legs.

Application Method

Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21. After wet abrasive blasting the Belzona 5831 was applied to the corroded areas above the waterline.

Belzona Facts

The surface tolerant properties of Belzona 5831 made it the ideal solution for these difficult access conditions. The product provides excellent adhesion to surfaces both in the splash zone and underwater.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve