Big Vacuum Oven Repair With Belzona 1593

ID: 8481

Industry: Chemical & Petrochemical Customer Location: Slovakia
Application: TCC-Tanks and Chemical Containment Application Date: 2019

Areas

Substrate: Steel

Products: * Belzona 1593,

* Belzona 9111 (Cleaner Degreaser),

Problem

The problem was: steel prickles inside which keep the oven insulation are degraded from acids throughout the life. Oven needed the protection against acids in high temperature.









Photograph Descriptions

- * 1. It was necessary to erect up scaffolding.,
- * 2. Steel prickles were coated too.,
- * 3. 2nd coat of Belzona 1593 applied.,
- * 4. Oven ready to use.,

Application Situation

They have used product Belzona 1593 for a vacuum oven in 2017. Because it was good and quick repair (several days) they made decision to use Belzona 1593 also for bigger construction - 675 m2.

Application Method

The application was performed in accordance with Belzona system leaflet TCC-5. After blasting and cleaning, the oven was applied with Belzona 1593 in 2 layers. The first coat of Belzona 1593 was applied at 375 microns. After 12 hours the second coat was applied at 375 microns. Complete coating was finished in 2 days.

Belzona Facts

Quick repair (several days)in high quality saves to customer big money.

1158 kg of Belzona 1593 was used.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com