

Big Vacuum Oven Repair With Belzona 1593

ID: 8481

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona 1593 ,
* Belzona 9111 (Cleaner Degreaser) ,

Customer Location: Slovakia
Application Date: 2019

Problem

The problem was: steel prickles inside which keep the oven insulation are degraded from acids throughout the life. Oven needed the protection against acids in high temperature.



Photograph Descriptions

- * 1. It was necessary to erect up scaffolding. ,
- * 2. Steel prickles were coated too. ,
- * 3. 2nd coat of Belzona 1593 applied. ,
- * 4. Oven ready to use. ,

Application Situation

They have used product Belzona 1593 for a vacuum oven in 2017. Because it was good and quick repair (several days) they made decision to use Belzona 1593 also for bigger construction - 675 m2.

Application Method

The application was performed in accordance with Belzona system leaflet TCC-5. After blasting and cleaning, the oven was applied with Belzona 1593 in 2 layers. The first coat of Belzona 1593 was applied at 375 microns. After 12 hours the second coat was applied at 375 microns. Complete coating was finished in 2 days.

Belzona Facts

Quick repair (several days) in high quality saves to customer big money.

1158 kg of Belzona 1593 was used.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

