

# Belzona furniture repair

ID: 8482

Industry: *Buildings & Structures*  
Application: *ENC-Engines and Casings*  
Substrate: *Chipboard*  
Products: *\* Belzona 1212 ,*

Customer Location: *Slovakia*  
Application Date: *2019*

## Problem

*The user needed to use this wardrobe immediately, without any dismantling, with repair for a long time.*



## Photograph Descriptions

- \* 1. Ripped out door hinge ,
- \* 2. Belzona 1212 application ,
- \* 3. Installation in short time ,
- \* 4. Ready to use ,

## Application Situation

After long time using was the wardrobe door hinge ripped out

## Application Method

Application was carried out using adapted Know-How System Leaflet ENC-2.

## Belzona Facts

User knows Belzona products from industry using. He needed quick, good and long- standing repair. Belzona 1212 was his genuine solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve