

Belzona Prevents Slips & Trips by using a Positive Grip Coating System

ID: 8534

Industry: *Commercial Facilities*
Application: *FPA-Floor Problem Areas*
Substrate: *Aluminium*
Products: ** Belzona 4411 (Granogrip). ,*

Customer Location: *Bern, Switzerland*
Application Date: *May 2019*

Problem

The customer wanted a coating that was both visible and tangible, as the loading ramp can be raised to 1.15m.



Photograph Descriptions

- * 1). Original condition without Belzona ,
- * 2). Security coating and marking area with Belzona 4411 ,

Application Situation

Aluminium checker plate loading ramp.

Application Method

The application was carried out in accordance with an adapted version of Belzona System Leaflet FPA-08.

The surface was initially prepared using appropriate power tools. It was then coated using Belzona 4411, followed by the incorporation of Granogrip prior to being over coated with a second layer of Belzona 4411.

Belzona Facts

Belzona 4411 not only provided a visually striking coating that would raise visual awareness but thanks to the incorporation of aggregate fillers also provided a physically grippy surface making employees aware of the risk area they are operating within.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve