

# BELZONA RE-SURFACES WATER PARK FLOORS

ID: 858

Industry: General Industry

Customer Location: Water Park - Oklahoma

Application: FPA-Floor Problem Areas

Application Date: May 2007

Substrate: Concrete

Products: Belzona® 5111 (Ceramic Cladding) <br> Belzona® 9221 (Surefoot Aggregate White)

## Problem

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.



## Photograph Descriptions

- \* Bathroom floors before application. ,
- \* Bathroom floors after Belzona® 5111 was applied. ,
- \* Outside surfaces before application. ,
- \* Outside surfaces after Belzona® 5111 application. ,

## Application Situation

Bathroom floors and outside surfaces in a water park.

## Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8.

## Belzona Facts

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

