

BELZONA RE-SURFACES WATER PARK FLOORS

ID: 858

Industry:	General Industry	Customer Location:	Water Park - Oklahoma
Application:	FPA-Floor Problem Areas	Application Date:	May 2007
Substrate:	Concrete		
Products:	Belzona® 5111 (Ceramic Cladding) Belzona® 9221 (Surefoot Aggregate White)		

Problem

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.



Photograph Descriptions

- * Bathroom floors before application. ,
- * Bathroom floors after Belzona® 5111 was applied. ,
- * Outside surfaces before application. ,
- * Outside surfaces after Belzona® 5111 application. ,

Application Situation

Bathroom floors and outside surfaces in a water park.

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8.

Belzona Facts

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

