

# Belzona prevents water damage on a hospital roof

ID: 8629

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Metallic Joints*  
Products: *\* Belzona 3121 (MR7) ,*

Customer Location: *Alabama*  
Application Date: *2021*

## Problem

*Rainwater was penetrating into the building*



## Photograph Descriptions

- \* 1. Original condition of the guttering ,
- \* 2. Application in progress ,
- \* 3. Completed application ,

## Application Situation

Rainwater was filling the gutters and entering behind the flashing into the building.

## Application Method

The application was cleaned of any loose material and degreased. The first layer of Belzona 3121 (MR7) was applied and the reinforcement sheet stipled in. Then the 2nd coat was applied and left to cure.

## Belzona Facts

Belzona offered an effective method of stopping any further leaks without the need to replace any of the guttering or flashing.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve