

Belzona protects pumps for water treatment plant

ID: 8631

Industry: Water / Wastewater
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona 1331 ,

Customer Location: US
Application Date: 2021

Problem

Pump linings suffer from erosion and corrosion over time due to exposure to the process stream. A lining resistant to erosion was required



Photograph Descriptions

* 1-3. Completed application ,

Application Situation

Water treatment pumps required protection

Application Method

Belzona 1331 was applied to the grit-blasted internals of the pumps

Belzona Facts

This was the second set of pumps to be protected by Belzona as they had no problems with their first set upon inspection, a few years after the initial installation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve