

# SUMP REPAIR WITH BELZONA AT YEAST PLANT

ID: 866

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona® 4111 (Magma Quartz)

Customer Location: Yeast Producer, Memphis, TN  
Application Date: March 2007

## Problem

After years of running 24 hours a day, 7 days a week the sump had erosion and corrosion from chemical attack at the water level.



## Photograph Descriptions

\* Sump prior to repair , \* Sump under repair , \* Sump after repair , \* Sump after repair ,

## Application Situation

Sump receiving waste water from the plant.

## Application Method

This application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

## Belzona Facts

The Belzona® 4111 will hold up to the the chemical attack providing long life to the sump. The Belzona solution provided the customer the ability to be back on-line in under 24 hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025