

SUMP REPAIR WITH BELZONA AT YEAST PLANT

ID: 866

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: *Belzona® 4111 (Magma Quartz)*

Customer Location: *Yeast Producer, Memphis, TN*
Application Date: *March 2007*

Problem

After years of running 24 hours a day, 7 days a week the sump had erosion and corrosion from chemical attack at the water level.



Photograph Descriptions

* Sump prior to repair , * Sump under repair , * Sump after repair , * Sump after repair ,

Application Situation

Sump receiving waste water from the plant.

Application Method

This application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

Belzona Facts

The Belzona® 4111 will hold up to the the chemical attack providing long life to the sump. The Belzona solution provided the customer the ability to be back on-line in under 24 hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve