

BELZONA REPAIRS BIODIESEL COLUMN


ID: 867

Industry: Chemical & Petrochemical
Application: CEP-Centrifugal Pumps
Substrate: Stainless Steel
Products: Belzona® 4301 (Magma CR1 Hi-Build)

Customer Location: Biodiesel Producer, Memphis, TN
Application Date: November 2006

Problem

Due to stress on a flange there was a crack at the weld causing Biodiesel to leak. This was 130 feet above the ground.



Photograph Descriptions

* The column to be repaired , * Column under repair , * Repaired area on column , * Repaired area close-up ,

Application Situation

Biodiesel Column

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3 & 6.

Belzona Facts

The Belzona solution offered the customer quick turn-around, without the expense of having to empty the column which they would have had to do if welding.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve