

# BELZONA REPAIRS BIODIESEL COLUMN

ID: 867

Industry: Chemical & Petrochemical  
Application: CEP-Centrifugal Pumps  
Substrate: Stainless Steel  
Products: Belzona® 4301 (Magma CR1 Hi-Build)

Customer Location: Biodiesel Producer, Memphis, TN  
Application Date: November 2006

## Problem

Due to stress on a flange there was a crack at the weld causing Biodiesel to leak. This was 130 feet above the ground.



## Photograph Descriptions

\* The column to be repaired , \* Column under repair , \* Repaired area on column , \* Repaired area close-up ,

## Application Situation

Biodiesel Column

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3 & 6.

## Belzona Facts

The Belzona solution offered the customer quick turn-around, without the expense of having to empty the column which they would have had to do if welding.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve