Belzona protects tank from external corrosion

ID: 8684

Industry: Food & Drink

Application: TCC-Tanks and Chemical Containment

Areas

Substrate: Steel

Products: * Belzona 5811 (Immersion grade),

Problem

External corrosion and chemical attack of the existing coating







Customer Location: South Africa

Application Date: 2021



Photograph Descriptions

* 1. Tank prior to surface preparation 2. Tank during surface preparation 3. Tank post surface preparation 4. Completed Application ,

Application Situation

A tank required protection from external corrosion at a food production facility.

Application Method

The surface was grit blasted and Belzona 5811 applied per IFU and system leaflet TCC-03

Belzona Facts

Belzona 5811 offers cost-effective protection from environmental and chemical attack, which will help extend the lifespan of this piece of equipment

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve