

BELZONA PROTECTS HOT WATER TANKS

ID: 871

Industry: Heating, Ventilation & Air Conditioning
Application: TCC-Tanks and Chemical Containment Areas




Customer Location: State Correctional Facility, Missouri
Application Date: February 2007

Substrate: Steel

Products: * Belzona® 5811 (Immersion Grade),
* Belzona® 1111 (Super Metal),

Problem

Severe internal corrosion



Photograph Descriptions

- * The tank inside the Powerhouse ,
- * View of the internal corrosion ,
- * Contractor applying 2nd coat of Belzona® 5811 ,
- * Technical Consultant inside the finished tank 2 days later ,

Application Situation

Hot water generation tanks within the Powerhouse.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

This application saved over \$60,000 against cost of replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve