

# EXPANSION JOINT AT HOSPITAL SEALED WITH BELZONA

ID: 879

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete*  
Products: *Belzona® 4111 (Magma Quartz)* <br /> *Belzona® 2221 (MP Fluid Elastomer)*

Customer Location: *Hospital, Missouri*  
Application Date: *2007*

## Problem

*Expansion joints in the hospital had become a tripping hazard*



## Photograph Descriptions

\* View of joint with kick plate removed , \* Application of Belzona® 4111 , \* Application of Belzona® 2221 , \* Completed application ,

## Application Situation

Expansion joints in corridor in need of repair

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and -6.

## Belzona Facts

The hospital needed a fast-curing and reliable method for repairing expansion joints that were creating trip hazards for patients.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve