

BELZONA REPAIRS SCHOOLS CHILLER

ID: 880

Industry: *Buildings & Structures*

Application: *HEX-Heat Exchangers*

Substrate: *Carbon Steel*

Products: ** Belzona® 1311 (Ceramic R-Metal) ,*

** Belzona® 1321 (Ceramic S-Metal) ,*

Customer Location: *Elementary School, St. Louis, Missouri*

Application Date: *2007*

Problem

Years of service had caused extensive corrosion on the chiller tube sheet face.



Photograph Descriptions

- * Corroded tube sheet face ,
- * Application in progress ,
- * Completed application ,
- * Completed application ,

Application Situation

Corroded chiller face

Application Method

Application was completed in accordance with Belzona System Leaflet HEX-1.

Belzona Facts

School officials were aware of Belzonas reputation for quality and reliability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve