Belzona Weatherproofs Instrumentation Control Roof

ID: 8875

Industry: Application: Substrate: Products:

Chemical & Petrochemical RPA-Roof Problem Areas Bituminous Roofing Felt * Belzona 3111 (Flexible Membrane), * Belzona 3921 (GSC Surface Conditioner), * Belzona 9311 (Reinforcement Sheet),

Customer Location: Caen, France Application Date: September 2022

Problem

The roof covered in gravel had been leaking water into the building for years. This issue worsened after the installation of a new skylight over 12-months ago, causing serious damage to the buildings internal walls.



Photograph Descriptions

- * 1). Roof after the gravel was removed.,
- * 2). Close-up of are where roofing felt had to be removed due to rot. ,
- * 3). Post-application of Belzona Stripe Coating on all edges and entry-points around the skylight.,
- * 4). Finished application with 2x coats of Belzona 3111 and Reinforcement Sheet. ,

Application Situation

Building roof (240m²) of an Instrumentation & Control office within a Petrochemical Depot.

Application Method

The application was carried out in accordance with Belzona System Leaflet RPA-01 & RPA-02.

Belzona Facts

The client unfortunately had no alternative due to the building being in an ATEX rated zone, and no other company being able to

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are FS 695214 ISO 14001:2015 EMS 695213 Management System.

manufactured under an ISO 9000 Registered Quality

www.belzona.com



supply a cold-applied solution with such a quick turnaround due to the wet season looming in.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

EMS 695213

ISO 9001:2015 Belzona products are FS 695214 manufactured under an ISO ISO 14001:2015 9000 Registered Quality EMS 695213 Management C Management System.

www.belzona.com

