

BELZONA REPAIRS NEW HEAVY EQUIPMENT TIRE

ID: 889

Industry: *General Industry*

Customer Location: *Equipment Dealership, South Central Kansas*

Application: *SHM-Solids Handling Machinery*

Application Date: *June, 2007*

Substrate: *Rubber*

Products: ** Belzona® 2311 (SR Elastomer) ,*

Problem

When the transport unloaded this brand new loader, the tire was damaged.



Photograph Descriptions

- * Damaged portion of the tire ,
- * Roughened surface ,
- * Surface conditioned ,
- * Tire rebuilt with Belzona® 2311 ,

Application Situation

New front end loader being delivered to the local dealership.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The surface was prepared with a roughing brush and conditioned with Belzona® 2911 (QD Conditioner). The gouges in the rubber tire cover were rebuilt with Belzona® 2311.

Belzona Facts

The Belzona repair was completed quickly and its excellent adhesion and abrasion resistance will ensure it continues to perform in service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve