

BELZONA SEALS THE GAP

ID: 8950

Industry: *Steel & Metal Processing*
Application: *FPA-Floor Problem Areas*
Substrate: *Carbon steel*
Products: *Belzona 4311 (Magma CR1)*


Customer Location: *SPAIN*
Application Date: *2017*

Problem


ANTI-ACID TILE FLOOR FAILURE CAUSES DAMAGE AND LIFTING OF TILES, DUE TO THE RECURRING FAILURE IN THE JOINTS BETWEEN TILES.



INITIAL CONDITION



SURFACE PREPERATION



APPLICATION COMPLETED

Application Situation

THROUGH THE BELZONA SOLUTION SEAL THESE JOINTS AND PROTECT THE ENTIRE FLOOR THUS CONSIDERABLY INCREASING ITS USEFUL LIFE

Application Method

- 1- CLEAN THE AREA TO BE REPAIRED WITH BELZONA® 9411
- 2- SURFACE PREPERATION TO GIVE PROFILE
- 3- THE JOINTS ARE COVERED WITH TWO COATS OF BELZONA® 4311 UNTIL LEAVING THE FLOOR AT THE SAME LEVEL

Belzona Facts

BELZONA WAS ABLE TO OFFER A SOLUTION TO EXTEND THE LIFE OF THE TILED APPLICATION AND OREVENT INGRESS OF ACID THROUGH THE JOINTS.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve