

# Belzona repairs sprinkler tank

ID: 8952

Industry: Food & Drink

Customer Location: Scotland

Application: TCC-Tanks and Chemical Containment Areas


Application Date: February 2023

Substrate: Carbon steel

Products: Belzona 1161 (Super UW-Metal), Belzona 9611 (ES-Metal)

## Problem

A pinhole leak had developed on the side of a sprinkler tank



Leak on tank



Initial surface preparation



Leak sealed with Belzona 9611 & additional surface preparation carried out



Plate bonded in place with Belzona 1161

## Application Situation

A cold applied repair was required to seal the leak & provide long term reinforcement to the damaged area

## Application Method

The initial area was first prepared back to bare metal & the leak was sealed with Belzona 9611. Once this was done the larger area was prepared using an angle grinder. A plate was then bonded in place using Belzona 1161 UW Metal

## Belzona Facts

By using the Belzona repair system the repair was able to be completed without damaging the tank's internal lining.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve