

Belzona lines Cooling Pipework for a large Steel Manufacturer

ID: 8993

Industry: Steel & Metal Processing
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel
Products: Belzona 5811 (Immersion Grade)

Customer Location: Normande, France
Application Date: November 2020

Problem

The cooling pipework had suffered corrosion due to course and seawater being used as the cooling fluid.



Pipework pre-refurbishment.



Pipework mid-application of Belzona 5811.



Finished internal & external lining application using Belzona 5811.



Finished internal & external lining application using Belzona 5811.

Application Situation

Cooling pipework (100m long x Ø1.4m) within a Steel Manufacturing Plant for a multi-stage long-term project.

Application Method

The distributor applied Belzona 5811 by Airless Spraying to increase application speed and provide a more even DFT. The application was carried out in accordance with a modified version of Belzona System Leaflet VPF-02.

Belzona Facts

The customer has previously used Belzona 5811 and therefore has proven trust within the provided solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve