

External Coating for Airport Jet Fuel Pipeline

ID: 9008

Industry: Oil & Gas
 Application: VPF-Valves, Pipes and Fittings
 Substrate: Carbon steel
 Products: Belzona 5831 (ST-Barrier)

Customer Location: Dubai, UAE
 Application Date: December 2022

Problem

The facility manager responsible for the airport's infrastructure found problems related to the jet fuel pipeline. Corrosion has been detected, posing a significant risk to the safety and reliability of the pipeline.



Original condition of the corroded pipeline



Application in progress



Application completed



Pipeline fully coated for corrosion protection

Application Situation

Jet fuel pipelines are a critical component of airport infrastructure and any problems must be addressed as soon as possible. Corrosion and erosion weaken pipelines and increase the risk of leakage. This not only poses a safety hazard to the airport, but can also lead to environmental pollution and significant economic losses.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-2 and two coats of Belzona 5831 was applied. As hot work was prohibited, manual surface preparation was carried out. No damage was caused by this process.

Belzona Facts

Belzona 5831 was chosen because it allowed minimum level of surface preparation, as there were concerns about damaging the pipe during surface preparation. Also because it can coat surfaces contaminated with oil. The asset remained operational during the application. This helped avoid expensive shutdowns and downtime just for repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA[®]
 Repair • Protect • Improve