

Belzona Stopped Pipe Leak

ID: 9040

Industry: Oil & Gas
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel
Products: Belzona 1981 (SuperWrap II), Belzona 9111 (Cleaner Degreaser), Belzona 9611 (ES-Metal)

Customer Location: Hungary
Application Date:

Problem

There were a cooling water pipe with leaking holes



Leaking hole



Surface preparation



Stopped leaking



Strengthen pipe section

Application Situation

It was a test application instead of welding.

Service pressure: 4 bar

Temperature: 10°C

Application Method

Surface preparation (MBX)

Cleaning (B9111)

Stop leaking (B9611)

Strengthen the pipe (SuperWrap II)

Belzona Facts

It was a test application instead of welding.

They would like to try the SuperWrap system on a high pressure gas pipe too.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2024