

Belzona repairs worn stairs in a school built in 1901

ID: 9056

Industry: Buildings & Structures

Customer Location: Zagreb, Croatia

Application: FPA-Floor Problem Areas

Application Date: August 2022

Substrate: Other

Products: Belzona 4111 (Magma-Quartz), Belzona 4151 (Magma-Quartz Resin), Belzona 4911 (Magma TX Conditioner)

Problem

An elementary school built in 1901 was being rebuilt after severe earthquakes that hit Zagreb in 2020. Construction company was our customer and they approached us with a problem of worn stone stairs that represented risk for children.



Loss of thickness on a stair due to 120 years of wear, represents a risk of falling and injury.

A stair rebuilt to its original level using Belzona 4111

A view on one of staircases in the school with several stairs repaired.

Situation after 8 months. We applied a final coat of Belzona 4151 with white stone dust and our customer abraded stairs in order to increase safety.

Application Situation

Customer needed a solution that would offer both safety and aesthetic criteria. We offered to rebuild damaged stairs with Belzona 4111 and apply final coat with Belzona 4151 and did a trial application in May 2022. Customer didn't find a solution that would match safety criteria of Belzona 4111 and we got the job despite not giving the desired exact aesthetic match.

Application Method

We installed a wooden support on front side of the stairs and then abraded the surface with electric grinders. Then we conditioned the surface with Belzona 4911 (using brush) and applied Belzona 4111 using a trowel. After full cure of Belzona 4111 we abraded surface once more and applied Belzona 4151 with addition of fine white dust in amount that produced color desired by customer.

Belzona Facts

Customer didn't find a solution that would match safety criteria of Belzona 4111 and we got the job in spite of not giving an exact aesthetic (colour) match. Also, all other alternatives were much more time consuming, and customer had only three weeks to finish

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

the job before the beginning of school year.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

