

Belzona Tank Base Sealing Seals out the weather

ID: 9072

Industry: Chemical & Petrochemical

Customer Location: Spain

Application: GSS-Gaskets, Seals and Shims

Application Date: January 2023

Substrate: Concrete

Products: Belzona 3211 (Lagseal), Belzona 3921 (GSC Surface Conditioner)

Problem

The areas round the base of the tanks were deteriorating and required protection from the elements, to prevent moisture ingress under the tanks.



Photo of a tank prior to application.



Photo of a tank prior to application.



Application in progress.



One of the tanks with the tank base sealing system installed.

Application Situation

Belzona offered a fast turnaround for the tanks in the timeframe required by the operator, offering future protection of the tanks.

Application Method

Belzona 3211 was applied as per system leaflet GSS-03.

Belzona Facts

Belzona offered a solution allowing for moisture ingress to be mitigated, helping reduce any future metal loss of the tank base.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve