

# Belzona Tank Base Sealing Seals out the weather

ID: 9072

Industry: Chemical & Petrochemical

Customer Location: Spain

Application: GSS-Gaskets, Seals and Shims

Application Date: January 2023

Substrate: Concrete

Products: Belzona 3211 (Lagseal), Belzona 3921 (GSC Surface Conditioner)

## Problem

*The areas round the base of the tanks were deteriorating and required protection from the elements, to prevent moisture ingress under the tanks.*



Photo of a tank prior to application.



Photo of a tank prior to application.



Application in progress.



One of the tanks with the tank base sealing system installed.

## Application Situation

Belzona offered a fast turnaround for the tanks in the timeframe required by the operator, offering future protection of the tanks.

## Application Method

Belzona 3211 was applied as per system leaflet GSS-03.

## Belzona Facts

Belzona offered a solution allowing for moisture ingress to be mitigated, helping reduce any future metal loss of the tank base.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve