

# Belzona Repairs Leaking Elevator Pit at Apartment Complex


ID: 9110

**Industry:** Buildings & Structures  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** Belzona 4111 (Magma-Quartz), Belzona 4911 (Magma TX Conditioner), Belzona 5811 (Immersion Grade)


**Customer Location:** Greensboro North Carolina  
**Application Date:** March 2022

## Problem

Elevator Pit was leaking really bad from around the shaft area and from under a metal plate. The pit was not passing inspection by the state of North Carolina and was going to be shut down and taken out of service. It was the only elevator in a 4 story apartment building.




Elevator Pit



Visual Damage



Application in progress



Complete application

## Application Situation

It was a very costly repair and took several days. They had tried many times using other materials to stop the leak.

## Application Method

We cleaned the surface and grinded out all the old repair material. We discovered the leaking area and applied a vacuum to the area to maintain a dry surface. Application of Belzona 4111 to entire area on and around the metal shaft plate. Coating of Belzona 5811 applied to entire area including the walls.

## Belzona Facts

It was very expensive and difficult situation, but Belzona solution fixed the problem where other solutions failed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2025

  
**BELZONA**  
Repair • Protect • Improve