

Internal Floating Roof (IFR) Repair - Belzona Florida

ID: 9177

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Aluminum
Products: Belzona 1121 (Super XL-Metal)

Customer Location: Port Canaveral, Florida
Application Date: November 2023

Problem

Customer needed to repair their IFR (Internal Floating Roof) cable guides because corrosion issues we're chronic and an easy repair needed to be found.



Area being prepped.



1121 product being mixed.



1121 being applied to the piece that will be bonded.



Finished application.

Application Situation

They needed an adhesive that they could trust to bond the new aluminum pieces in place. Belzona 1121 was chosen for its outstanding performance characteristics, ease of use and extended working life

Application Method

Standard surface preparation through the use of an angle grinder and a carbide grinding wheel.

Belzona Facts

Belzona 1121 allowed the customer to replace nearly 40 units and just a few hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve