

BELZONA REPAIRS AND SEALS IRON GUTTER

ID: 918

Industry: Buildings & Structures

Application: RPA-Roof Problem Areas

Substrate: Cast Iron

Products: * Belzona® 3111 (Flexible Membrane) ,
<div>Belzona® 3921 (GSC Conditioner)</div>
<div>Belzona® 9311 (Reinforcing Sheet)</div>

Customer Location: Logistics Factory, Lancashire - UK

Application Date: April 2007

Problem

The cast iron had over time corroded and the joints deteriorated allowing water to enter the internal fabric of the building.



Photograph Descriptions

- * Blocked and corroded gutter ,
- * Gutter drained ready for preparation ,
- * Belzona fully reinforced Flexible Membrane system ,
- * Completed application ,

Application Situation

Traditional cast iron gutter 0.5 meters wide by 64 meters long

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

Belzona Facts

The cost of the Belzona was a fraction of the replacement cost of the cast iron gutter which was the other alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve