

# BELZONA REPAIRS AND SEALS IRON GUTTER

ID: 918

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*

Customer Location: *Logistics Factory, Lancashire - UK*  
Application Date: *April 2007*

Substrate: *Cast Iron*

Products: *\* Belzona® 3111 (Flexible Membrane) ,*  
*<div>Belzona® 3921 (GSC Conditioner)</div>*  
*<div>Belzona® 9311 (Reinforcing Sheet)</div>*

## Problem

*The cast iron had over time corroded and the joints deteriorated allowing water to enter the internal fabric of the building.*



## Photograph Descriptions

- \* Blocked and corroded gutter ,
- \* Gutter drained ready for preparation ,
- \* Belzona fully reinforced Flexible Membrane system ,
- \* Completed application ,

## Application Situation

Traditional cast iron gutter 0.5 meters wide by 64 meters long

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

## Belzona Facts

The cost of the Belzona was a fraction of the replacement cost of the cast iron gutter which was the other alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

