

Plate bonding in marine bulkhead

ID: 9185

Industry: *Marine*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Carbon steel*
Products: *Belzona 1111 (Super Metal)*

Customer Location: *Scotland*
Application Date: *March 2020*

Problem

An area of corrosion had led to wall thinning on a bulkhead. Welding was undesirable due to the confined space & close proximity of fuel.



Belzona 1111 applied to plate



Substrate wet out



Plate applied to the corroded area



Overview of installation area

Application Situation

The application was completed in 1 day with minimal hazard to the crew onboard.

Application Method

The area was prepared with an MBX Bristle blaster. Belzona 1111 was then used to wet out the substrate & the plate. The plate was then pushed into position to reinforce the corroded area.

Belzona Facts

The Belzona repair saved time & reinforced the area long term

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve